



UNIVERSITY OF ALBERTA
ENVIRONMENT, HEALTH & SAFETY

Containment Level 3 Sanitary Drain Line Incident November 15, 2018

Christi Andrin, Ph.D
Associate Biosafety Officer



Advancing research and
learning with trusted guidance
and tools

CL-3 Sanitary Drain Line Incident

- I. Summary of Incident
- II. Investigation Findings
 - a. Causal Factors
 - b. Root Cause
- III. Corrective Actions
 - a. Development of unique monitoring system
- IV. Lessons Learned



November 15th . . . within the infrastructure support area for the CL3



1 F&O Millwrights discover water on floor and pouring from the ceiling

Plumbers verify with Biosafety that it is safe to enter

2 Water leaked on equipment, ventilation systems, electrical control panels





-
-
- 3** Hydroclave holding tanks found FULL with water backing up through the drainage system



4

Weight of water caused the several joints on the drain line to fail; some lines broke



Source of water was NOT clear

- No water running or leaking fixtures within CL3 facility
- No alarms on the autoclaves or indications of concern



CL3 Autoclave identified as source of the water


Air valve controlling the cooling water valve FAILED on one autoclave

- very rare type of failure
- water valve forced open
- domestic cold water running continuously at building pressure



INFRASTRUCTURE/EQUIPMENT



- Integrity of drainage system – improper installation, inadequate supports



- Autoclave valve failure - no feedback to autoclave systems regarding the failed valve(s)



- Hydroclave system was offline with high level alarms inoperative for impending maintenance



- Moisture sensor position ineffective



Severity of incident was due to communication gaps

- Facilities personnel unaware of maintenance activities being conducted by faculty technical support personnel
- Technical support personnel unaware of how after market safety features on the Hydroclaves functioned (no documentation)




I. Repair damaged drain lines

- heat seal pipe joints
- pressure test system with water, not air



II. install leak detection system



III. Install additional moisture sensor(s) around Hydroclaves

IV. Improve communications across university units regarding:

- Training
- Maintenance – scheduling and outcomes
- On-site hazard/risk assessment based decisions



At risk for this type of incident when:

- research equipment is integrated with building infrastructure
- AND
- a disconnect occurs between responsible parties

Significant costs

- lost research, building and equipment repairs, re-testing systems, administrative burden (reporting, documentation, licensing)

Communication and Collaboration KEY to protect research and infrastructure alike.



Questions

